



Gearbox for CNC machines with driver




- V+ : Motor power input (12 - 35 Vdc)
- GND : Motor power ground
- Vcc : Optocoupler anode (+5V computer)
- DIR : Left / Right input
- STEP : Step puls input (low > 8 uS , 50 Khz max)
- EN : Enable input (No input is run)

- DIP SW : Microstep resolution
 - : $\frac{1}{1}$ = 1 on , 2 on
 - : $\frac{1}{2}$ = 1 off, 2 on
 - : $\frac{1}{4}$ = 1 on , 2 off
 - : $\frac{1}{16}$ = 1 off, 2 off

CNC Steppermotor with driver and gearbox for CNC machines



Front view



Side view