


CNC DC Servomotor DCM50207 / DCM50207D



Aansluitingen / connections / anslusse DCM50207D-1000 DC CNC servomotor

Zwart = Black	= Zwart	= Noir	: Phase A	(output from encoder)
Blaauw = Blue	= Blau	= Bleu	: Phase /A	(output from encoder)
Geel = Yellow	= Gelb	= Jaune	: Phase B	(output from encoder)
Groen = Green	= Grün	= Vert	: Phase /B	(output from encoder)
Rood = Red	= Rot	= Rouge	: Vcc (+5V)	(Power in to encoder)
Wit = White	= Weiss	= Blanc	: GND	(Power in to encoder)

Aansluitingen / connections / anslusse DCM50207-1000 DC CNC servomotor

Zwart = Black	= Zwart	= Noir	: (E)GND	(Power in to encoder)
Blaauw = Blue	= Blau	= Bleu	: Phase B	(output from encoder)
Geel = Yellow	= Gelb	= Jaune	: Phase A	(output from encoder)
Groen = Green	= Grün	= Vert	: Index/NC	
Rood = Red	= Rot	= Rouge	: Vcc (+5V)	(Power in to encoder)

